


CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)		
Element	Cd	Description	Element	Cd	Description
Style	03	Colonial	Bsmt Area	1680	
Model	01	Residential	Bsmt Type	04	
Grade	07	Very Good	Unfin Area	0.00	Full
Stories	2				
Occupancy	1				
Exterior Wall 1	14	Wood Shingle			
Exterior Wall 2					
Roof Structure	03	Gable			
Roof Cover	03	Asphalt			
Interior Wall 1	05	Drywall			
Interior Wall 2					
Interior Floor 1	12	Hardwood			
Interior Floor 2	14	Carpet			
Heat Fuel	02	Oil			
Heat Type	05	Hot Water			
AC Type	01	None			
Bedrooms	4				
Full Baths	2				
Half Baths	1				
Extra Fixtures	1				
Total Rooms	7				
Bath Style	02	Average			
Kitchen Style	02	Average			
Extra Kitchens	0				
Fireplaces	1				
Extra Openings	0				
Gas Fireplaces	0				
Sq Ft Fin Bsmt	423				
FBM Quality	05	Living Area			
Foundation	06	Poured Conc			
Bsmt Garage	2				
Bsmt Area	1680				

CONDO DATA				
Parcel Id		C	Owne	
			B	S
Adjust Type	Code	Description	Factor%	
Condo Flr				
Condo Unit				

COST / MARKET VALUATION	
Net Other Adj	45,560
Replace Cost	730,919
Year Built	1983
Effective Year Built	2000
Depreciation Code	G
Remodel Rating	
Year Remodeled	
Depreciation %	21
Functional Obsol	
External Obsol	
Trend Factor	1.000
Condition	
Condition %	
Percent Good	79
Cns Sect Rcnld	577,400
Dep % Ovr	
Dep Ovr Comment	
Misc Imp Ovr	
Misc Imp Ovr Comment	
Cost to Cure Ovr	
Cost to Cure Ovr Comment	



OB - OUTBUILDING & YARD ITEMS(L) / XF - BUILDING EXTRA FEATURES(B)										
Code	Description	L/B	Units	Unit Price	Yr Blt	Cond. Cd	% Gd	Grade	Grade Adj.	Appr. Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Floor Area	Eff Area	Unit Cost	Undeprec Value
BAS	First Floor	1,580	1,580	1,580	221.58	350,103
BSM	Basement	0	1,680	336	44.32	74,452
FOP	Open Porch	0	12	2	36.93	443
FUS	Finished Upper Story	1,136	1,136	1,136	221.58	251,719
PTO	Patio	0	336	17	11.21	3,767
WDK	Deck	0	216	22	22.57	4,875
Ttl Gross Liv / Lease Area		2,716	4,960	3,093		685,359

